WATER QUALITY INFORMATION

Marion Utilities conducts regular testing to monitor its treatment process and drinking water quality. The table below shows contaminants that were detected in 2023 water samples or in the most recent testing done for that contaminant. Contact Marion Utilities for a list of all tested contaminants. No violations were identified.

Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants that do not necessarily pose a health risk. More information about contaminants and potential health effects can be obtained by calling the EPA's Safe Drinking Water Hotline at (800) 426-4791.

| Contaminant | Date Sampled | MCLG | Action Level | 90 th Percentile | # Sites Over Action Level | Typical Source |
|--|--------------------|----------|-----------------------------|-----------------------------|------------------------------|---|
| Lead and Copper (Results remain on this report for 3 years from the test date or when the test is repeated) | | | | | | |
| Copper (ppm) | 06/14/23 | 1.3 | 1.3 | 0.053 | 0 | Corrosion of household plumbing |
| Lead (ppb) | 06/14/23 | 0 | 15 | 1.730 | 0 | Corrosion of household plumbing |
| Contaminant | Collection Date | Result | Range of Levels Detected | MCLG | MCL | Typical Source |
| INORGANIC CONTAMINANTS (Results remain on this report for 3 years from the test date or when the test is repeated) | | | | | | |
| Barium (ppm) | 03/23/23 | <0.0040 | 0.0040 | 2 | 2 | Erosion of natural deposits |
| Chromium (ppb) | 03/23/23 | 0.0034 | 0.00040 | 100 | 100 | Erosion of natural deposits |
| Fluoride (ppm) | 03/23/23 | 0.58 | 0.20 | 4 | 4 | Erosion of natural deposits |
| Nickel (ppm) | 03/23/23 | 0.0011 | 0.0010 | 0.1 | 0.1 | Erosion of natural deposits |
| Sodium (ppm) | 03/23/23 | 37.80 | 0.20 | N/A | N/A | Erosion of natural deposits |
| UNREGULATED CONTAMINANTS (Detected during UCMR 4 Test must remain on this report for 5 years from the test date) | | | | | | |
| Bromochloroacetic Acid (ppb) | 01/08/19 | 0.509 | 0.303 - 0.715 | N/A | N/A | Disinfection byproduct |
| Dichloroacetic acid (ppb) | 01/08/19 | 1.615 | 1.21 - 2.02 | N/A | N/A | Disinfection byproduct |
| Dibromoacetic acid (ppb) | 01/08/19 | 0.302 | 0.302 | N/A | N/A | Disinfection byproduct |
| Manganese (ppb) | 01/08/19 | 1.36 | 1.36 | N/A | N/A | Erosion of natural deposits |
| Bromide (ppb) | 01/08/19 | 86.75 | 81.6 – 91.9 | N/A | N/A | Naturally occurring disinfection byproduct precursor |
| Total Organic Carbon (ppb) | 01/08/19 | 1760 | 1630 - 1890 | N/A | N/A | Naturally occurring disinfection byproduct precursor |
| UNREGULATED CONTAMINANTS (Detected during UCMR 5 Test) | | | | | | |
| PFOA (ug/L) | 12/18/23 | <0.0040 | 0.0040 | N/A | N/A | Consumer, commercial, and industrial products |
| PFOS (ug/L) | 12/18/23 | <0.0040 | 0.0040 | N/A | N/A | Consumer, commercial, and industrial products |
| RADIOACTIVE CONTAMINANTS (Results remain on this report for 5 years from the test date or when the test is repeated) | | | | | | |
| Beta/photon emitters (mrem/yr) | 06/04/20 | 0.9 | 0.9 - 0.9 | 0 | 4 | Decay of natural and man-made deposits |
| Gross alpha excluding radon & uranium (pCi/L) | 06/04/20 | 0.01 | 0.01 - 0.01 | 0 | 15 | Erosion of natural deposits |
| RESIDUAL DISINFECTANT & DISINFECTANT | TION BY PRODU | JCTS | | | | |
| Chlorine Residual (ppm) | 2023 | 2.96 Avg | 2.16 - 3.29 | MRDLG = 4 | MRDL = 4 | Water additive used to control microbes |
| Haloacetic acid (ppb) | 2023 | 1.26 | <1.0 – 1.26 | No Goal for the Total | 60 | Byproduct of drinking water disinfection |
| Total Trihalomethanes (ppb) | 2023 | 0.83 | 0.79-0.87 | No Goal for the Total | 80 | Byproduct of drinking water disinfection |

Avg: Regulatory compliance with some MCL's is based on running annual average of monthly samples.

Maximum Contaminant Level or MCL: The highest level of a contaminant that is allowed in drinking water. MCLs are set as close to the MCLGs as feasible using the best available treatment technology.

Maximum Contaminant Level Goal or MCLG: The level of contaminant in drinking water below which there is no known or expected risk to health. MCLGs allow for a margin of safety.

Maximum Residual Disinfectant Level or MRDL: The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control of microbial contaminants.

ppm = milligrams per liter or parts per million - or one ounce in 7,350 gallons of water.

ppb = micrograms per liter or parts per billion - or one ounce in 7,350,000 gallons of water.

pCi/L = one trillionth of a curie, mrem = millirems per year (a measure of radiation absorbed by the body), ug/L = micrograms/liter.

GENERAL INFORMATION

The sources of drinking water (both tap and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally-occurring minerals and radioactive material, and can pick up substances resulting from the presence of animals or from human activity. Contaminants that may be present in source water include:

- (A) Microbial contaminants, such as viruses and bacteria, which may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife.
- (B) Inorganic contaminants, such as salts and metals, which can be naturally-occurring or result from urban storm runoff, industrial or domestic wastewater discharges, oil and gas production, mining, or farming.
- (C) Pesticides and herbicides, which may come from a variety of sources such as agriculture, stormwater runoff, and residential uses.
- D) Organic chemical contaminants, including synthetic and volatile organic chemicals, which are by-products of industrial processes and petroleum production, and can also come from gas stations, urban storm water runoff, and septic systems.
- (E) Radioactive contaminants, which can be naturallyoccurring or be the result of oil and gas production and mining activities.

In order to ensure that tap water is safe to drink, EPA prescribes regulations which limit the amount of certain contaminants in water provided by public water systems. FDA regulations establish limits for contaminants in bottled water which must provide the same protection for public health.

Some people may be more vulnerable to contaminants, including the immuno-compromised such as persons undergoing chemotherapy, persons with organ transplants, people with HIV/AIDS or other immune system disorders, some elderly, and infants can be particularly at risk from infections. These people should seek advice about drinking water from their health care providers. EPA/CDC guidelines on appropriate means to lessen the risk of infection by Cryptosporidium and other microbial contaminants are available from the Safe Drinking Water Hotline at (800) 426-4791.

GROUNDWATER

Marion Utilities pumps about 3.7 million gallons of water per day from wells in the Teays River Valley. Many years ago, glaciers carved out this valley and filled the area with glacial sediment. This has made an excellent groundwater source for the City of Marion.



Marion Utilities works hard to protect our groundwater sources and treatment processes. Once pumped, the groundwater is softened, filtered, treated with chlorine, and pumped into the drinking water system. For more information on preventing groundwater contamination, please visit: www.marionutilities.com.

BACTERIAL MONITORING

Marion Utilities conducts routine monitoring for presence of harmful bacteria within the water supply. This monitoring ensures that we provide the best public health protection possible by finding and fixing any potential vulnerabilities to contamination as soon as they occur.

In 2016, the Revised Total Coliform Rule (RTCR) went into effect and strengthened limits on E. coli, a specific indicator for contamination. It also increased the response required by a positive coliform sample and established a more active response to this indicator if found. In over 371 samples taken in 2023, no presence of total coliform or E. coli bacteria was found.

LEAD AND YOUR PLUMBING

If present, elevated levels of lead can cause serious health problems, especially for pregnant women and young children.

Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. Marion Utilities is responsible for providing high quality drinking water, but cannot control the variety of materials used in home plumbing components.

When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for thirty seconds to two minutes before using water for drinking or cooking.

If you are concerned about lead in your water, information about that, testing methods, and steps you can take to minimize exposure is available from the

Safe Drinking Water Hotline or at:

http://www.epa.gov/safewater/lead

If you have any questions about the contents of this report, please contact

Robin Shrader at (765) 664-2391

OR JOIN US at our
Marion Utilities Service Board meetings
1540 N. Washington St. on the 1st and 3rd
Thursday of each month at 5:30 pm.



2024 Annual Water Quality Report

Your service provider for

Drinking Water ●

Wastewater ● Stormwater

Solid Waste • Recycling

The mission of Marion Utilities is to bring added value to the city of Marion by providing excellent customer service, maintaining the highest of standards for the lowest possible cost, and promoting environmental stewardship to ensure the future of our community.